

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:05 - 23.09.2014

GPS 55.4287,10.4578

Skal fjernes/rengøres



08:06 - 23.09.2014

GPS 55.4287,10.4578

Huller i limtræ - Skal spartles

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:07 - 23.09.2014

GPS 55.4288,10.4578

Fuge i samling og males 1 gang



08:09 - 23.09.2014

GPS 55.4286,10.4577

Skal fastgøres

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:10 - 23.09.2014

GPS 55.4286,10.4577

Ikke i samme niveau



08:10 - 23.09.2014

GPS 55.4286,10.4577

Skal rengøres

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:15 - 23.09.2014

GPS 55.4287,10.4577

Rep



08:15 - 23.09.2014

GPS 55.4287,10.4577

Rep

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang


23.09.2014



08:16 - 23.09.2014

GPS 55.4287,10.4577

Brændt af



08:18 - 23.09.2014

GPS 55.4287,10.4577

Huller i fuge

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang


23.09.2014



08:21 - 23.09.2014

GPS 55.4287,10.4577

Lille bad ved entre - skidt på væg




08:25 - 23.09.2014

GPS 55.4286,10.4579

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:26 - 23.09.2014

GPS 55.4287,10.4579

Skidt på malingen



08:26 - 23.09.2014

GPS 55.4287,10.4579

Skidt under gulvtæppet

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:31 - 23.09.2014

GPS 55.4287,10.4578

Renses af - stort bad



08:32 - 23.09.2014

GPS 55.4287,10.4578

Rep stort bad

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:32 - 23.09.2014

GPS 55.4287,10.4579

Rep - stort bad



08:33 - 23.09.2014


GPS 55.4287,10.4579

Rep bad - stort bad

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:34 - 23.09.2014

GPS 55.4286,10.4579

Stort bad



08:35 - 23.09.2014

GPS 55.4286,10.4579

Løber og skidt på maling -
soveværelse

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:36 - 23.09.2014

GPS 55.4286,10.4578

Skidt i dør , så den er stram -
smøreres og justeres



08:36 - 23.09.2014

GPS 55.4286,10.4578

Loft rep - stue

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:37 - 23.09.2014

GPS 55.4286,10.4577

Rep - stue



08:38 - 23.09.2014

GPS 55.4286,10.4578

Justeres - skrue skal skrues i

HusCompagniet Fyn
Karsten Jakobsen

Ryleholmen 18
Mangelgennemgang

23.09.2014



08:39 - 23.09.2014

GPS 55.4286,10.4578

Tørres af - stue



08:57 - 23.09.2014

GPS 55.4287,10.4578

Savet i kabel - Efter montering af
emhætte